

GENWAL COAL COMPANY

September 21, 1992

Mr. Daron Haddock
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, UT 84180-1203

RECEIVED

SEP 23 1992

DIVISION OF
OIL GAS & MINING

RE: Permit #ACT 015-032
Genwal Coal Company
Submitted Revisions - Mine Plan
Chapter 7

Dear Mr. Haddock:

After our last complete inspection with Jim Smith, it was found that a discrepancy existed within Chapter 7, page 7-37. Paragraph 4 speaks of a drill hole #DH-2 and references Plate 6-1 for the location of this hole. This has now been revised to show the correct drill hole designation, DH-1, and the correct plate, Plate 3-2, that shows location.

Please find enclosed 14 copies of a single page, 7-37, to replace the existing 7-37 of the MRP. The Plate 3-2 enclosed is for your reference only and no changes have been made to this plate.

Should you have any questions or need additional information, please contact me at 687-9813.

Sincerely,

GENWAL COAL COMPANY

R. Jay Marshall
R. Jay Marshall
Chief Engineer

Larry W. Johnson
Larry W. Johnson
Engineer

tr